

General Motors LLC Recalls January 1 to May 31, 2014

NHTSA ID Number	Date of Notification	Make	Model	Model Year	Number of Vehicles
14V-007	01-13-14	Chevrolet GMC	Silverado Sierra	2014	324,970

Brief Description of Defect

Mfg. Campaign No. 14008 - Exhaust. DOM: N/A. On vehicles with 4.3l or 5.3L engines, when vehicle is idling in cold temperatures, exhaust components can overheat and may melt nearby plastic parts resulting in engine fire. Correct by reprogramming engine control module.

14V-047	02-10-14	Chevrolet	Cobalt	2005-10	2,190,934
			HHR	2005-11	
		Pontiac	G5, Solstice	2007-10	
		Saturn	Ion	2003-07	
			Sky	2007-10	

Brief Description of Defect

Mfg. Campaign No. 13454/14063/14092 - Ignition Switch. DOM: 6/02-5/11. This defect can affect safe operation of airbag system. Until this recall is performed, customers should remove all items from their key rings, leaving only ignition key. Key fob (if applicable), should also be removed from key ring. Weight on key ring and/or road conditions or some other jarring event may cause ignition switch to move out of run position, turning off engine. If key is not in run position, airbags may not deploy if vehicle is involved in crash, increasing risk of injury. Correct by replacing ignition switch. Note: until recall repairs have been performed, it is very important that customers remove all items from their key rings, leaving only vehicle key. Key fob should also be removed from key ring.

14V-092	02-21-14	Buick	Enclave, Lacrosse,	2014	355
			Regal, Verano		
		Chevrolet	Cruze, Impala,		
		GMC	Malibu, Traverse Acadia		

Brief Description of Defect

Mfg. Campaign No. 14048 -Transmission/FMVSS 102 & 114. DOM: 1/14-2/14. Transmission shift cable adjuster may disengage from transmission shift lever. As such, these vehicles fail to meet FMVSS 102. They also fail to meet FMVSS 114. If vehicle's shift cable disengages from transmission shift lever, driver may be unable to shift gear positions and indicated shift position may not represent gear position vehicle is in. Should disengagement occur while vehicle is being driven, when driver goes to stop and park vehicle, driver may be able to shift lever to "park" position, but vehicle transmission may not be in "park" gear position. If vehicle is not in "park" position vehicle may roll away as driver and other occupants exit vehicle or anytime

thereafter. vehicle rollaway increases risk of injury to exiting occupants and bystanders. Correct by inspecting and replace any affected transmission shift cable adjusters.

14V-116 03-17-14 Cadillac XTS 2013-14 63,903

Brief Description of Defect

Mfg. Campaign No. 14062

DOM: 2/12-3/14. Cavity plug on brake booster pump connector may dislodge allowing corrosion of brake booster pump relay connector. corrosion of brake booster pump relay connector may cause resistive short and melt connector, increasing risk of fire. Correct by apply sealant to connector cavity plugs, re-route vacuum pump vent hose and replace front body wiring harnesses as needed.

14V-117 03-17-14 Chevrolet Express 2009-14 303,013
 GMC Savana 2009-14

Brief Description of Defect

Mfg. Campaign No. 14082 - Dash Panel/FMVSS 201. DOM: 1/09-3/14. On vans with gross vehicle weight rating of 10,000 pounds and less and with front passenger airbags, during frontal impact below airbag deployment threshold, if unbelted front passenger's head hits instrument panel above where passenger airbag is located, panel may not sufficiently absorb impact. As such, these vehicles fail to meet FMVSS 201. In event of crash below airbag deployment threshold, unbelted front passenger seat occupant has increased risk of injury. Correct by modify passenger instrument panel.

14V-118 03-17-14 Buick Enclave 2008-13 1,176,407
 Chevrolet Traverse 2009-13
 GMC Acadia 2008-13
 Saturn Outlook 2008-10

Brief Description of Defect

Mfg. Campaign No. 14030 - Airbag. DOM: N/A. Increased resistance in driver and passenger seat mounted side impact airbag wiring harnesses may result in side airbag and seat belt pretensioners not deploying in event of crash. Failure of side impact airbags and seat belt pretensioners to deploy in crash increase risk of injury to driver and front seat occupant. Correct by replacing affected harness connections with soldered connections

14V-144 03-27-14 Cadillac ELR 2014 656

Brief Description of Defect

Mfg. Campaign No. 14087 - ESC/FMVSS 126. DOM: N/A. On vehicles not equipped with adaptive cruise control, electronic stability control (esc) system software may inhibit esc diagnostics, preventing system from alerting driver that esc system is partially or fully disabled. Vehicles fail to meet FMVSS 126. If driver is not alerted to esc malfunction they may continue driving with disabled esc system which may result in loss of directional control, resulting in

crash. Correct by recalibrate electronic brake control module (ebcm)

14V-151	03-31-14	Chevrolet	Cruze	2013-14	174,046
---------	----------	-----------	-------	---------	---------

Brief Description of Defect

Mfg. Campaign No. 14079 - Half Shaft. DOM: 11/12-3/14. On vehicles with 1.4L turbo engine, right front half shaft may fracture and separate. If half shaft fractures and separates while driving, vehicle would lose power and coast to stop. If vehicle with fractured half shaft is parked without parking brake applied, vehicle could move unexpectedly. Either condition can result in crash. (This is expansion of recall 13V-452 in which some vehicles were repaired using defective parts and will be remedied again under this campaign.) Correct by inspecting and replacing right half shaft as needed.

14V-152	03-31-14	Chevrolet	Silverado	2014	489,936
			Suburban, Tahoe	2015	
		GMC	Sierra	2014	
			Yukon	2015	

Brief Description of Defect

Mfg. Campaign No. 14121- Transmission Oil Cooler. DOM: N/A. Vehicles with 6-speed automatic transmission (feature code MYC) may have transmission oil cooler line that is not securely seated in fitting. If line is not securely seated and transmission oil leaks from fitting, oil could contact hot surface and cause vehicle fire. Correct by inspecting transmission oil cooler line connection and repairing as needed.

14V-153	03-31-14	Chevrolet	Cobalt	2010	1,340,447
			HHR	2009-10	
			Malibu Maxx	2004-06	
			Malibu	2004-09	
		Pontiac	G6	2005-09	
		Saturn	Aura	2008-09	
			Ion	2004-07	

Brief Description of Defect

Mfg. Campaign No. N140115 - P/Steering. DOM: 4/03-6/10. Sudden loss of electric P/steering (eps) assist could occur at any time while driving. If P/steering assist is lost, greater driver effort would be required to steer vehicle at low speeds, resulting in crash. Correct by performing one of four bulletins. Correct by replacing EPS motor under Bulletin 14115 for 2004-07 Saturn Ion, 2009-10 Chevrolet HHR, 2010 Chevrolet Cobalt. Correct by replacing torque sensor assembly under Bulletin 14116 for 2004-06 Chevrolet Malibu, Malibu Maxx, 2005-06 Pontiac G6 and 2008-09 Chevrolet Malibu, Pontiac G6, Saturn Aura (built from March 1, 2008, through June 27, 2008). Correct by replacing torque sensor assembly and EPS motor controller unit under Bulletin 14117 for 2008 Chevrolet Malibu, Pontiac G6, Saturn Aura all built from February 1, 2008, through February 28, 2008. Correct by replacing EPS motor controller unit under Bulletin 14118 for 2008 Chevrolet Malibu, Pontiac G6, Saturn Aura built from October 1, 2007, through January 31, 2008. Note: GM Bulletin 14119 will be implemented for 2006-08 and early

production 2009 Chevrolet HHR (non-turbo) and 2003 Saturn Ion to provide EPS motor replacement for life of vehicle.

14V-168 04-09-14 Pontiac Vibe 2009-10 23,247

Brief Description of Defect

Mfg. Campaign No. N/A- Airbag. DOM: 1/08-7/09. Steering column assembly contains electrical connections to driver's airbag module housed in spiral cable assembly, which includes flexible flat cable. Due to shape and location of cable's retainer, cable could become damaged when steering wheel is turned. If cable is damaged, connectivity to driver's airbag module could be lost and airbag deactivated. failure of driver's airbag to deploy in crash that typically necessitates deployment increases risk of injury to driver. Correct by replacing spiral cable assembly.

14V-171	04-10-14	Chevrolet	Cobalt	2005-10	2,191,014
			HHR	2006-11	
		Pontiac	G5	2007-10	
			Solstice	2006-10	
		Saturn	Ion	2003-07	
			Sky	2007-10	

Brief Description of Defect

Mfg. Campaign No. 14113,14133 - Transmission Key Lock. DOM: 6/02-5/11. Key can be removed from ignition when ignition is not in "off" position and vehicle could roll away: (a) for automatic transmission, if transmission is not in "park" position; or (b) for manual transmission, if parking brake is not engaged and transmission is not in "reverse" position. Rollaway can result in crash and occupant or pedestrian injuries. Correct by replacing defective ignition cylinder on vehicles that have not previously had ignition cylinder replaced with redesigned part and, if necessary, cutting and re-learning two ignition/door keys for each vehicle. For vehicles that were built with redesigned ignition cylinder or had ignition cylinder replaced with redesigned part, correct by cutting and, if necessary, re-learning two ignition/door keys for each vehicle. Note: until vehicle has been remedied, owners and operators are advised that when exiting, to be sure that vehicle is in "park," or in case of manual transmission, that vehicle is in "reverse" position and parking brake is engaged.

14V-212 04-25-14 Cadillac SRX 2013 50,571

Brief Description of Defect

Mfg. Campaign No. 14132 - Transmission Control Module. DOM: 5/12-7/13. Vehicles with 3.6L engines may have three to four second lag in acceleration due to transmission control module programming which can result in crash. Correct by reprogramming transmission control module.

14V-213 04-25-14 Chevrolet Silverado HD 2015 51
GMC Sierra HD

Brief Description of Defect

Mfg. Campaign No. 14067 - Fuel Pipe. DOM: 2/14-2/14. On vehicles with diesel engines and dual fuel tanks, fuel pipe connections on both sides of diesel fuel transfer pump may not be properly torqued which may result in diesel fuel leak and fire. Correct by tightening fuel pipe connections to proper torque.

14V-223 04-30-14 Buick Enclave 2014 51,640

Brief Description of Defect

Mfg. Campaign No. 14007 - ECM. DOM: 3/13-8/13. Engine control module (ecm) software may cause fuel gauge to read inaccurately. This may result in vehicle unexpectedly running out of fuel and stalling, resulting in crash. Correct by reprogramming ecm to correct fuel gauge reading.

14V-224 04-30-14 Saturn Aura 2007-08 56,214

Brief Description of Defect

Mfg. Campaign No. 14152 - Transmission Shift Cable. DOM: 4/06-10/07. On vehicles with four speed automatic transmission, transmission shift cable may fracture. If transmission shift cable fractures while vehicle is being driven, when driver goes to stop and park vehicle, driver will not be able to shift lever to "park" position, or remove ignition key. If vehicle is not in "park" position vehicle may roll away as driver and other occupants exit vehicle or anytime thereafter. vehicle rollaway resulting in injury to exiting occupants and bystanders. Correct by replacing shift cable assembly and mounting bracket

14V-246 05-14-14 Chevrolet Silverado, Tahoe 2014 477
 GMC Sierra 2014

Brief Description of Defect

Mfg. Campaign No. 14204 - Tie Rod. DOM: 5/13-3/14. Tie rod threaded attachment may not be properly tightened to steering gear rack. improperly tightened tie rod attachment may allow tie rod to separate from steering rack, resulting in loss of steering, increasing risk of vehicle crash. Correct by inspecting inner tie rods to make sure that they are correctly tightened, replacing steering gear, as necessary. Note: owners are advised not to drive their vehicles until they have been inspected and repaired. Owners should contact GM to have their vehicles towed to dealership.

14V-247 05-14-14 Chevrolet Malibu 2014 140,067

Brief Description of Defect

Mfg. Campaign No. 14201 - Brake/FMVSS 135. DOM: 6/13-5/14. Vehicles with 2.5L engine and auto stop/start option may experience complete loss of brake vacuum assist, disabling hydraulic boost assist. Vehicles fail to meet FMVSS 135. If hydraulic boost assist is disabled, slowing or stopping vehicle will require additional brake pedal effort and lengthened stopping distance which may result in crash. Correct by updating electronic brake control module software.

14V-251 05-14-14 Chevrolet Corvette 2005-07 103,158

Brief Description of Defect

Mfg. Campaign No. 13146 - Electrical Center. DOM: 3/04-6/07. Underhood bussed electrical center (ubec) housing can expand and cause headlamp low beam relay control circuit wire to bend. If wire is repeatedly bent, it may fracture causing a loss of low beam headlamp illumination. loss of low beam headlamp illumination will decrease driver's visibility, as well as vehicle's conspicuity to other motorists, increasing risk of a crash. Correct by replacing ubec housing unit

14V-252 05-14-14 Chevrolet Malibu 2004-2012 2,440,524
Maxx 2004-07
Pontiac G6 2005-2010
Saturn Aura 2007-2010

Brief Description of Defect

Mfg. Campaign No. 13036 - Body Control Module. DOM: 3/03-10/12. Increased resistance in body control module (bcm) connection may result in voltage fluctuations in brake apply sensor (bas) circuit. These fluctuations can cause one or more conditions: brake lights to illuminate without brake pedal being pushed; brake lights to not illuminate when pedal is pushed; difficulty disengaging cruise control; moving gear shifter out of 'park' position without pushing brake; and disablement of crash avoidance features such as traction control, electronic stability control, and panic braking assist features. Any of above failure can result in crash. Correct by attaching wiring harness to bcm with spacer, apply dielectric lubricant to both bcm and harness connector and bas and harness connector, and will relearn brake pedal home position.

14V-253 05-15-14 Cadillac CTS 2014 19,225

Brief Description of Defect

Mfg. Campaign No. 14157 - W/S Wiper. DOM: 6/13-2/14. If vehicle is turned off with wiper functionality left on and wipers become restricted, such as when covered in ice or snow, and vehicle's battery goes dead and needs to be jump started, upon being jump started, wipers will be inoperative which can result in crash. Correct by replacing front wiper module.

14V-259 05-16-14 Cadillac Escalade ESV, Escalade 2015 2,838

Brief Description of Defect

Mfg. Campaign No. 14220 - Airbag Module/FMVSS 208. DOM: 4/14-5/14. Airbag module is secured to chute adhered to backside of instrument panel with insufficiently heated infared weld. This may result in partial deployment of front passenger airbag in crash. Vehicles fail to meet FMVSS 208. Airbag that only partially deploys may result in occupant injury. Correct by replacing instrument panel right side upper trim panel. Note: owners are advised that until vehicle has been remedied, occupants should not sit in front passenger seat position.

14V-260 05-19-14 Chevrolet Optra 2004-08 213

Brief Description of Defect

Mfg. Campaign No. 14093 - Headlight. DOM: N/A. Heat may be generated in headlamp switch or daytime running light (drl) module and heat could melt headlamp switch or drl module. This may result in vehicle fire. Remedy for recall campaign is under development.

14V-261 05-19-14 Chevrolet Aveo 2004-08 218,000

Brief Description of Defect

Mfg. Campaign No. 14236 - DRL Module. DOM: N/A. Heat may be generated within drl module located in center console in instrument panel, which could melt drl module. This may result in vehicle fire. Remedy for recall campaign is under development.

14V-265 05-20-14 Chevrolet Silverado HD 2015 58
GMC Sierra HD 2015

Brief Description of Defect

Mfg. Campaign No. 14208 - Fuse Block. DOM: 1/14-2/14. retention clips that attach fuse block to vehicle body can become loose allowing fuse block to move out of position. If this occurs, exposed conductors in fuse block may contact mounting studs or other metallic components, causing a short to ground event. This could result in arcing condition, and combustible materials located nearby could ignite and result in engine compartment fire. Correct by inspecting fuse block to verify that it is properly secured, repairing it as necessary.

14V-266 05-20-14 Buick Enclave 2009-2014 1,339,355
Chevrolet Traverse 2009-2014
GMC Acadia 2009-2014
Saturn Outlook 2009-10

Brief Description of Defect

Mfg. Campaign No. 14187 - Seat Belt. DOM: 4/08-5/14. Flexible steel cable that connects seatbelt to front outboard seating positions may fatigue and separate. If steel cable becomes fatigued and separates, seatbelt may not properly restrain seat occupant resulting in injury in crash. Correct by inspecting and, if necessary, repairing and replacing lap pretensioner.