

The Embedded Systems Experts

11/6/13

MICHAEL BARR

Embedded Software Expert

Electrical Engineer (BSEE/MSEE)

Experienced Embedded Software

■
Developer

Named inventor on 3 patents



Consultant & Trainer (1999-present)

■ Embedded Software Process and
■ Architecture for reliability


Various industries (e.g., pacemakers,
industrial controls)

Former *Adjunct Professor*

- 2 University of Maryland 2000-2003 (Design and Use of Operating Systems)
- 2 Johns Hopkins University 2012 (Embedded Software Architecture)




BOOKS BY MICHAEL BARR




1ed: 1999; 2ed:
2006

3
3



1ed:
2003



1ed: 2008; 2ed:
2012

EMBEDDED SYSTEMS DEFINED

“Embedded Systems”

- Electronics + software for a dedicated purpose
- Many billion more new embedded systems each year
microwave ovens, digital watches, pacemakers,
thermostats You are surrounded by them (like it or not;
safe or not)



Embedded systems in cars

Modern cars contain networks of embedded computers!

Anti-lock brakes, airbags, speedometer, GPS, radio, ...

4 Some carmakers brag over 100 microprocessors inside!

4 Each headlight, each mirror, each seat, ...

Toyota's Operating
Systems

MY REVIEW OF TOYOTA'S SOURCE CODE

Access to Toyota's "electronic throttle" source code

- In a secure room in Maryland
- Subject to confidentiality agreements
- For vehicle models with ETCS spanning ~2002-2010 model years
 - Camry, Lexus ES, Tacoma, and others
-

Approximately 18 months of calendar time with code

By a very experienced team of embedded systems experts

NASA must reach a clear-cut conclusion by the end of August.

So they are under a fair amount of pressure.

TOY-MDL05951378
TOY-MDL05951378P-0001


Building upon NASA's earlier source code review; digging deeper

EXAMPLE C LANGUAGE SOURCE CODE


function

```
int larger_of(int a, int b)
{
    if (a > b)
        return a; /* a contains the larger value */
    else
        return b; /* b contains the larger value */
}
```

ELECTRONIC THROTTLE CONTROL



TOYOTA'S ENGINE CONTROL MODULE (ECM)



Monitor Chip
("ESP-B2")
contains software

Main CPU
("V850")
contains software

8

SAFETY-CRITICAL SYSTEMS

Not all embedded systems can kill or injure people ...

- Those that can do harm are “safety-critical systems”

■
What could possibly go wrong?

- A glitch in the electronics (*random hardware faults will happen*)
- A bug in the software (*any reasonably complex software has bugs*)
- An unforeseen gap in the intended safety features
- Or all three: glitch activates bug and that slips thru safety gap

9

Toyota's Watchdog
Supervisor


Safety cannot be an afterthought; must be designed in

Redundancy and fault containment are key

ELECTRONIC THROTTLE CONTROL (ETCS)

“Toyota ETCS-i is an example of a safety-critical hard real-time system.”

- N



NASA, p.
13

10
10

11/6/13

SUMMARY OF 2005 CAMRY L4 CONCLUSIONS

Toyota's ETCS source code is of unreasonable quality

- Toyota's source code is defective and contains bugs
 - Including bugs that can cause unintended acceleration
- Code quality metrics predict presence of additional bugs

Toyota's fail safes are defective and inadequate

11 11 "House of cards" safety architecture

Barr St. John
Report

11/6/13

Random hardware and software faults are a fact of life

UNINTENDED ACCELERATION (UA)

I use the same definition as NHTSA and NASA:

- “any degree of acceleration that the vehicle driver did not purposely cause”

¹ In this report, “unintended acceleration” refers to the occurrence of any degree of acceleration that the vehicle driver did not purposely cause to occur. Contrast this with the term “sudden acceleration incident,” which refers to “unintended, unexpected, high-power accelerations from a stationary position or a very low initial speed accompanied by an apparent loss of braking effectiveness.” *An Examination of Sudden Acceleration*, DOT-TSC-NHTSA-89-1 at v. As used here, unintended acceleration is a very broad term that encompasses sudden acceleration as well as incidents at higher speeds and incidents where brakes were partially or fully effective, including occurrences such as pedal entrapment by floor mats at full throttle and high speeds and incidents of lesser throttle openings at various speeds.

NHTSA, p. vi

I also use the phrase “*loss of throttle control*”

■ Throttle controls airflow, which controls engine power

12

Barr St. John

12

Report

NASA DID NOT RULE OUT UA BY SOFTWARE

The NESC team identified two hypothetical ETCS-i failure mode scenarios (as opposed to non-electronic pedal problems caused by sticking accelerator pedal, floor mat entrapment, or operator misapplication) that could lead to a UA without generating a diagnostic trouble code (DTC): specific dual failures in the pedal position sensing system and a systematic software malfunction in the main central processor unit (CPU) that is not detected by the monitor system.

The second postulated scenario is a systematic software malfunction in the Main CPU that opens the throttle without operator action and continues to properly control fuel injection and ignition.

Because proof that the ETCS-i caused the reported UAs was not found does not mean it could not occur. However, the testing and analysis described in this report did not find that TMC

Due to system complexity which will be described and the many possible electronic hardware and software systems interactions, it is not realistic to attempt to “prove” that the ETCS-i cannot cause UAs. Today’s vehicles are sufficiently complex that no reasonable amount of analysis or testing can prove electronics and software have no errors. Therefore, absence of proof that the ETCS-i has caused a UA does not vindicate the system. From calendar year 2005 to 2010 TMC

THERE ARE DEFECTS IN TOYOTA'S ETCS

2005 Camry L4 source code and in-vehicle tests confirm:

Some critical variables are not protected from corruption

Mirroring was not always done

➤➤ NASA didn't know this (*believed mirroring was always done*)

No hardware protection against bit flips

➤➤ NASA didn't know this (*was told main CPU's RAM had EDAC*)

Sources of memory corruption are present

Stack overflow can occur

➤➤ NASA didn't know this (*was told stack less than half used*)


There are software bugs

➤➤ NASA found bugs (*and Barr Group has found others*)

Barr St. John
Report

1
4

ETCS SOFTWARE MALFUNCTION



SOFTWARE MALFUNCTIONS HAPPEN

All kinds of embedded systems experience partial software malfunction from time-to-time

- e.g., most other apps working, but phone calls go direct to voice mail “Have you tried rebooting it?”



1
6


Barr St. John
Report



11/6/13

The 2005 Camry L4 software has

TOYOTA'S OPERATING SYSTEM (OSEK)




17

17

11/6/13

Barr Chapter Regarding
Toyota's Operating
Systems

OSEK'S CRITICAL DATA STRUCTURES




Barr Chapter Regarding
Toyota's Operating
Systems

18
18

11/6/13

MEMORY CORRUPTION AND TASK DEATH




Barr Chapter Regarding
Toyota's Operating
Systems

19
19

11/6/13

EXAMPLE OF UNINTENDED ACCELERATION



- Representative of task death in real-world
- Dead task also monitors accelerator pedal, so **loss of throttle control**
- ✓✓ Confirmed in tests
- When this task's death begins with brake press (any amount), **driver must fully remove foot from brake to end UA**
- ✓✓ Confirmed in tests

SOFTWARE CAUSES OF MEMORY CORRUPTION

Type of Software Defect	Causes Memory Corruption?	Defect in 2005 Camry L4?
Buffer Overflow	Yes	Yes
Invalid Pointer Dereference/Arithmetic	Yes	Yes
Race Condition (a.k.a., “Task Interference”)	Yes	Yes
Nested Scheduler Unlock	Yes	Yes
Unsafe Casting	Yes	Yes
Stack Overflow	Yes	Yes

2
1

Barr Chapter
Regarding Software
Bugs

SPAGHETTI CODE DEFINED

space *n.* A logic 0 on an RS-232 link. Any voltage between -13 and +25 V. *See also* mark.

spaghetti code *n.* **Incomprehensible source code, typically including apparently meaningless jumps or gotos or a high degree of unnecessary coupling between modules.**

spawn *v.* To create a new thread of execution.

SPDT (as letters) *abbr.* A type of switch that has one actuator (pole) that connects to one of two contacts. Short for Single Pole, Double Throw. Used to select one of two conditions. *Compare to* SPST.



The schematic symbol for an SPDT switch makes its design and purpose clear.

spec (speck) *abbr.* *See* specification.

- Difficult to follow data/control paths
- Bugs likely to appear when modified
- Unnecessarily complex



Ganssle & Barr,
System Design Dictionary,
2003

TOYOTA'S SPAGHETTI CODE

3. Software assembly for power train ECU

After the 4th Steering Committee, rebuilding of engine control and actions for software assembly were started.

(1) Achievements

① Identification of current issues with software assembly Ongoing

- There are C sources for which there is no specification document. (e.g., communication related)
- Specification document and C source do not correspond one-to-one. (e.g., cruise, communication related)

② Activities to improve the spaghetti-like status of engine control application were started.

(Control structure reform has already started in Engine Div. In coordination with this, software structure reform will be carried out. As a first step, it has been decided to transfer two employees from Engine Div. and carry out trial with purge control.)

Because structure design is not being implement, a "spaghetti" state arises, both TMC and suppliers struggle to confirm overall situation

Without care, systems can quickly get too big and complex, and like dinosaurs, will eventually go extinct.



2
3

TOY-MDL04983219

TOY-MDL04983253
TOY-MDL04983252P-0002

TYPES OF SPAGHETTI CODE

Data-flow spaghetti

- Complex coupling between software modules and between tasks
- Count of global variables is a software metric for “tangledness”
 - 2005 Camry L4 has >11,000 global variables (NASA)

Control-flow spaghetti


Many long, overly-complex function bodies

Cyclomatic Complexity is a software metric for “testability”

2005 Camry L4 has 67 functions, scoring >50 (“untestable”)
Barr Chapter Regarding Toyota's Code

4 The throttle angle function scored over 100
Complexity
(unmaintainable)

STACK ANALYSIS FOR 2005 CAMRY L4



Barr Chapter
Regarding Toyota's
Stack Analysis

NASA'S VIEW ON RECURSION

NASA was concerned about possible stack

- Deeply nested recursion could exhaust the stack space, leading to memory corruption and run-time failures that may be difficult to detect in testing.

The question, then, is how to verify that the indirect recursion present in the ETCS-i does in fact terminate (i.e., has no infinite recursion) and does not cause a stack overflow.

For the case of stack overflow, the CPU in the ETCS-i does not have protected memory, and therefore a stack overflow condition cannot be detected precisely. It is likely, however, that overflow would cause some form of memory corruption, which would in turn cause some bad

It is not clear what impact recursion has with respect to the larger UA problem. Whether one recursive loop or two, there are other sites of recursion in the ETCS-i that remain unanalyzed.

... and NASA didn't know there was so little safety

- | Faced with this limitation, Toyota added an extra margin of safety allocating 4096 bytes for the ETCS-i stack—more than double the

2
6

NASA, Appendix A, pp. 20, 129-134

TOYOTA'S MAJOR STACK MISTAKES

Toyota botched its worst-case stack depth analysis

- Missed function calls via pointers (*failure to automate*)
 - Didn't include any stack use by library and assembly functions
 - Approximately 350 functions ignored
- HUGE: Forgot to consider OS stack use for context switching!**

safety critical embedded software

On top of that... Toyota used dangerous recursion

- A safety check that the cheaper 2005 Corolla ECM had!

2
7

11/6/13

Barr Chapter

And... Toyota failed to perform run-time stack
Regarding Toyota's

TOYOTA FAILED TO COMPLY WITH STANDARDS

Operating System Standards

“OSEK” is an international standard API

- Specifically designed for use in automotive software
- Multiple suppliers of OSEK operating systems

Compliance tests ensure compatibility across versions

-
-

Barr Chapter Regarding

Toyota's Operating Systems

2
8 But Toyota's Rx-OSEK850 version is non-
standard!!!

TOYOTA FAILED TO COMPLY WITH STANDARDS

Automotive Industry Coding Guidelines

MISRA-C - motor industry software reliability coding rules for C

- By 2004, “*the successes and global use of MISRA-C across automotive, aerospace, medical, and other industries has been*
- *staggering.”*

“In Japan, we have worked with representatives of JSAE, JAMA, ...”

-
-

From 2002-2004, Toyota said in public they followed MISRA-C

But NASA reported > 7,000 violations of *some* of the rules (p. 29)

I checked the full set and found > 80,000 in violations in 2005 Camry L4


Barr Chapter Regarding
Toyota’s MISRA-C
Violations

2
9

11/6/13

Toyota’s coding standard only has 11 MISRA-C rules

In the words of Toyota



3
0

VANALFEN006972 (Kawana,
2004)

TOYOTA FAILED TO COMPLY WITH STANDARDS

Internal Coding Standards

Toyota maintains a set of company internal coding rules

- Specifically for “power train” ECM software developers to follow
- **Mr. Ishii’s statement about 50% MISRA-C overlap was found false**

NASA reported Toyota didn’t follow *some* of its rules (p. 22)

- I found at least 32% of Toyota’s coding rules were violated
-

Enforcement is the most important part of having a rule

3

1

Barr Chapter Regarding
Toyota’s Coding
Standards
Demonstrates lack of engineering discipline at Toyota
Part of a larger pattern of inadequate software

TOYOTA ADMITS ETCS HAS SOFTWARE BUGS

A: When it comes to software, there are going to be bugs, and [that] is the case not just with Toyota but with [any] software in the automotive industry and any software. So the issue is not whether or not there is a bug but rather is the bug an important material bug.

- Ishii 5/24/12 Deposition, p. 91

Barr Chapter
Regarding Toyota's
Software Bugs

3
2
1 Indeed there are bugs, including "important material bugs"

11/6/13

NASA'S SOFTWARE AREAS OF CONCERN

NASA, Appendix B, pp. 36-39



= Defects Found by Barr Group





Figure B7-1. Software Error Fishbone Diagram

Barr Chapter
Regarding Task
Death and UA

TOYOTA'S DEFECTIVE "SAFETY LAYERS"



Barr Chapter Regarding Toyota's Watchdog Supervisor

3
4

LAYER 1: MIRRORING OF CRITICAL VARIABLES

Toyota's engineers sought to protect numerous variables against software- and hardware-caused corruptions

e.g., by "mirroring" their contents in a 2nd location



But FAILED TO MIRROR several key critical variables

OSEK's critical internal data structures

THE *target throttle angle* global

variable!

Barr Chapter Regarding


Toyota's Memory
Protections

Commands a part of the software to
open the throttle



Recalculated every 8 ms

THROTTLE COMMAND DESIGN



3

6

11/6/13

Barr Chapter Regarding
Toyota's Software
Architecture

UA VIA MEMORY CORRUPTION

Task X death causes loss of throttle control by driver

- Changes at the accelerator pedal have no effect on throttle
- angle Cruise control switches have no effect


■ Motor Control Task continues to drive throttle motor; engine powered

- Throttle could stick at last computed *throttle command*, or
- Change angle via corruption of *throttle command* global variable

Barr Chapter
Regarding Task
Death and UA

3
7
One corruption event can cause task death and open throttle

TOYOTA'S DEFECTIVE THROTTLE CONTROL



3
8

Barr Chapter
Regarding Toyota’s
Software Bugs

LAYER 2: DTCs AND FAIL-SAFE MODES

NASA talks about 5 fail-safe modes (pp. 79-83)

- Limp home modes 1-3 (*degrees of gas pedal sensor mistrust*)
- Idle mode fuel cut (*2,500 rpm limit at idle*)
- Engine off (*via several different “class 2” failures*)

However, all 5 fail-safes are in same Task X

Throttle control and fail-safes in same fault containment region

Unreasonable design; alternative structures well-known

Barr Chapter

Regarding Toyota's

Fail Safe Modes


39

39

LAYER 3: WATCHDOG SUPERVISOR

A “watchdog timer” is hardware to auto-reset software

- Healthy software should periodically “check-in” to prevent



With multiple tasks, health of all tasks must be checked

40
40

Barr Chapter Regarding
Toyota’s Watchdog
Supervisor

TOYOTA'S DEFECTIVE WATCHDOG DESIGN

Toyota's watchdog supervisor design is unreasonable

- Incapable, ever, of detecting death of majority of tasks
- Incapable of properly and reliably detecting CPU overload
- Allows vehicle misbehavior due to overloads lasting up to 1.5s
- Resets the watchdog timer hardware in a timer tick ISR
- Explicitly ignores and discards most operating system error codes

Ignoring error codes violates a MISRA-C rule (1998: #86; 2004: #16.10)

Reasonable design alternatives were well known

Indeed the primary purpose should've been to detect task death

Barr Chapter Regarding

Toyota's Watchdog

Supervisor

41

2005 Prius (HV-ECU) watchdog is better

41

“System Guards”

- All (3) useless after Task X death (don't know driver intent)



“Brake Echo Check”

- Depends on the driver to take action—after UA has already begun!

Sometimes a counter-intuitive/dangerous action

➤ ➤ Clearly this is not a “designed” fail-safe for UA or task

death Takes the wrong actions (*should've reset ECM not stalled*

car) Not 100% reliable

Barr Chapter

Regarding Toyota's

Monitor CPU

42

42

TOYOTA FAILED TO REVIEW MONITOR CPU

A: With respect to [the monitor CPU], the development process is completely different. When it comes to the source code that would be embedded in [the monitor CPUs] we, Toyota, don't receive them. ... there would not be a design review done on the software.

Q: Now, the monitoring software for the electronic throttle control system is in the [] ESP-B2 chip; correct?

A: Yes.
43

Barr Chapter
Regarding Toyota's
Monitor CPU

AGAIN: FAILED TO REVIEW MONITOR CPU!

The critical “monitor CPU” that checks the main CPU has never been independently reviewed

- Toyota doesn't even have a copy of the source code
- NASA didn't review that critical system component either

ESP-B2 source code was not provided to NASA

Barr Group has reviewed Denso's ESP-B2 source code

- Monitor CPU for 2005-2009 Camry L4 (and some other models)



44
44

Barr Chapter
Regarding Toyota's
Monitor CPU

11/6/13

MONITOR CPU IS LAST LINE OF UA DEFENSE

But ESP-B2 monitor CPU could have included a proper UA defense:

- IF (driver is braking & throttle is not closing) THEN reset ECM
Something is not right with the main CPU when that happens! Resets of main CPU barely noticeable at speed
- (brief rpm drop)
CRITICAL to ending UA in vehicles with potential vacuum loss



Per car cost to add this safety feature is \$0.00 (it's just bits) There was enough memory and CPU bandwidth for these instructions All of the required electrical inputs and outputs were already present In line with E-Gas Level 3 recommendations

Barr Chapter
Regarding Toyota's
Monitor CPU

45
45

TOYOTA'S DEFECTIVE SOFTWARE PROCESS

FMEA was incomplete; single points of failure are present

- Because: Toyota didn't adopt a formal safety process

Peer reviews not done on OS code and ESP-B2 code

- Because: Toyota didn't perform code reviews; used non-standard OSEK

Toyota's own "power train" coding standard not enforced

Because: Toyota didn't follow through with software suppliers



Watchdog supervisor doesn't detect most task's deaths

Generally costs less to push the limits than upgrade to faster CPU


If confident, why let NASA believe there was

No EDAC protection against hardware bit flips

Generally costs less to make memory chips without EDAC

46
46

TOYOTA'S INADEQUATE SOFTWARE PROCESS



- Toyota failed to exercise a safe standard of care for software
- Relied too much on vendors
- Lacked internal expertise

There is a process in place for hardware, but not software

➤➤ Inadequate supervision and training of software

- Process IN/OUT, timeframe not decided
- There are processes at Toyota yielding no knowledge.

➤ Large deviation in product quality among vendors.

Barr Chapter Regarding Toyota's Code Complexity

TOYOTA'S DEFECTIVE SAFETY CULTURE

From: Hideo Inoue.
To: [-] Masashi Takagi.
Cc: [-] Shigeyuki Kawana; hosotani@n1hs.tec.toyota.co.jp.
Bcc: [-].
Subject: Re: A quick report on Vice President Takimoto's failsafe progress report.

Sent: 9/26/2007 10:15 PM.

This is Inoue.

Kawana-san

What Takagi-san has written is right.
Takimoto-san was Positive [[sic]] to us.

In truth, technology such as failsafe is not part of the Toyota Engineering division's DNA, but isn't it good that it is recognized as one of the major strengths of Toyota in the system controls industry?

This time it is just an explanation, but I would definitely like him to experience it on an actual vehicle. Inputting this kind of information to Takimoto-san is important and I think passing along information with relative frequency is a good thing. It looks like he would become a good supporter so I believe at some point it is a good idea to pass our wishes along to executives.

In truth, technology such as failsafe is not part of the Toyota Engineering division's DNA, but isn't it good that it is recognized as one of the major strengths of Toyota in the system controls industry?

However, thinking about the future, continuing on as is will not be a good thing. We will need to benchmark companies such as Bosch to gauge shortcomings and strengths.

4
8

TOY-MDL016058888P-
0001

NASA SOUGHT WHAT BARR GROUP FOUND

1) Conditions necessary for Failure to Occur, Failure Mode	2) Failure Conditions and Failure symptoms found in Real World? Note 1	3) Physical or Electronic Evidence, Failure Detection	4) Range of throttle opening
Software unilaterally opens throttle with Accelerator released, Idle Fuel Cut not active, Watchdog serviced, no EDAC error, Sub-CPU does not Detect Failure	No, Cannot engineer a test. No place found in software where a single memory/variable corruption results in a UA	Theoretical Fault Escapes Detection	Openings up to wide open throttle conceptualized although not found in real world

“Single memory corruption results in UA” “Fault escapes detection”

- “No EDAC error” (*because there is no EDAC!*)
- “Idle fuel cut not active” (*because in same task*)
- “Watchdog serviced” (*because defective design*)
- Sub-CPU “does not detect failure” (*because not designed to*)

NASA p.
78

“Openings up to wide open throttle”

49

49

Barr St. John
Report

UNREASONABLE SINGLE POINTS OF FAILURE

Safety critical systems shouldn't have single points of failure

This is the normal mode of design in automotive industry



Toyota tried to mitigate such risks, including in software

But missed some dangerous single points of failure

Failed to prevent or contain faults ...

There are single points of failure in the ETCS

50

50

Some demonstrated in 2005 and 2008 Camry L4 vehicles

Barr St. John
Report

Unpredictable range of vehicle misbehaviors via task

death Other memory corruptions can be expected

THE TEST SPACE IS EFFECTIVELY INFINITE

There are >16 million combinations of task death

- Memory corruption can kill 1, 2, or all 24




Each task can die in thousands of ways

- Internal software states
- Vehicle operational states (e.g., cruise control, 50%)

Test “samples” so far

confirm etc.




vs. scenarios;

5
2

Claimed fail-safes inadequate!


Barr Chapter
Regarding Task
Death and UA

UA FOREVER IF BRAKE ON AT TASK DEATH




Vehicle speed

Gas pedal does not affect



Fail-safe acts only after driver removes foot (fully) from

Brake on (even lightly) at start of task



None of the "fail-safes" act > 30 seconds



CASE-SPECIFIC OPINIONS

ETCS misbehavior is more likely than other causes

- Car should have stopped in less distance if throttle not open
- (McCort) Eyewitness testimony of alert driver using brakes (Mrs. Schwarz)
- No evidence of pedal entrapment by a floor mat (*photos*)
- No mechanical problems found at any vehicle inspection (*experts*)
-

Cannot identify with 100% certainty the specific software defects

- Toyota's software design "deletes" evidence of software problems
- Restart car and engine is fine (*Toyota should have logged errors*)

5

4

11/6/13

More likely than not undetected Task X death

OTHER SIMILAR INCIDENT CRITERIA

Vehicles with substantially similar ETCS software

- e.g., 2005-2009 Camry



Incidents with no apparent mechanical cause

- Lack of support for floor mats trapping accelerator pedal
- No indication of any mechanical issue before or after

OSI Sources: NHTSA complaint database, Toyota FTRs, claims

5 Driver and witness statements describe UA

5

And no evidence contradicting correct use of pedals

Barr St. John
Report

TOYOTA'S EXPERT'S EVOLVING STATEMENTS

ETCS contains “layers of protection” (Jul 2012)

- True, but misses the key point: there are gaps thru those layers



Brake echo is a “designed fail-safe” (Sep 2012-Aug 2013)

No, IF it were “by design” the fail-safe

would NOT require the driver to act before the fail-safe! would

“It depends on how much fuel” (Sep 2013)

NEVER require removal of foot from brake pedal



counter-intuitive (in an emergency!) and likely to increase (!)

risk of harm

TOYOTA'S EXPERT HAS NOT REBUTTED

My Operating System

opinions/chapter *My Software Bugs*

opinions/chapter

My Memory Protections

opinions/chapter

My Software Architecture

opinions/chapter *My Watchdog Supervisor*

opinions/chapter

My Fail-Safe Modes opinions/chapter

My MISRA-C Violation

opinions/chapter *My Coding Standard*

Position of Dr. Kato on My Code

Complexity opinions/chapter *My*

Stack Analysis opinions/chapter