2007 to 2010 Model Year Tundra and 2008 to 2010 Model Year Sequoia Vehicles Air Injection Pumps and Air Switching Valves

Warranty Enhancement Notice

Re: <MY> < Tundra or Sequoia > <VIN>

CSC-10042935-2538

Dear [Tundra / Sequoia] Owner:

At Toyota, we are dedicated to providing vehicles of outstanding quality and value. As part of our continual efforts to meet your product expectations, Toyota would like to advise you of an extension to portions of your [Tundra/Sequoia] vehicle warranty.

Toyota cares about our customers

Toyota has received reports of customer concerns regarding the illumination of the check engine light (Malfunction Indicator Light) due to moisture/water in the Air Injection Pumps and/or Air Switching Valves in the engines of a number of these vehicles. To assist dealers in the diagnosis and repair of these vehicles a TSB has been released.

Some of the vehicles covered by the TSB may be outside of the Toyota's New Vehicle Limited Powertrain Warranty due to age and/or mileage. To assure customers that we stand behind our product, we are offering a warranty extension on the Air Injection Pumps and Air Switching Valves on 2007 to 2010 Tundra and 2008 to 2010 Sequoia vehicles.

Warranty Enhancement Details

The Air Injection Pumps and Air Switching Valves are covered by Toyota's New Vehicle Limited Powertrain Warranty for 5 years or 60,000 miles (whichever comes first) and by the California Emission Warranty* for 7 years or 70,000 miles (whichever comes first).

The Warranty Coverage Extension (CSP) for the Air Injection Pumps and Air Switching Valves for the condition described above will extend the warranty coverage to 10 years from the date of first use or 150,000 miles, whichever comes first. If the condition is verified, the dealer will replace the Air Injection Pumps and Air Switching Valves under the terms of this CSP.

Please note that damage incurred from abuse, a crash, vandalism or other similar events is not covered by the New Vehicle Limited Warranty or this Warranty Extension.

*The California Emission Warranty coverage only applies to certain states and certain model year/engine type Tundra and Sequoia vehicles. Please refer to your vehicle's Toyota Owner's Warranty Information Booklet for details and applicability.

What should you do?

If you have not experienced this condition, please insert this letter into your [Tundra's or Sequoia's]

Owner's Warranty Information Booklet for future reference.

If you experience a Malfunction Indicator Light (check engine light) "ON" condition, please contact any Toyota dealer and make arrangements for diagnosis and, if applicable, repair. Repairs of the Air Injection Pumps and/or Air Switching Valves that are diagnosed will be performed at NO CHARGE for up to 10 years from the vehicle's date of first use or 150,000 miles, whichever occurs first. Please present this notice to the Toyota dealer when you bring the vehicle in for your appointment.

The repair will take approximately 4 hours; however, depending upon the dealer's work schedule, it may be necessary to make the vehicle available for a longer period of time. At this time Toyota has a very limited number of parts available to support vehicle repairs; we apologize for any inconvenience this may cause. We wanted to advise you of this warranty extension and provide reimbursement instructions for previous repairs to help minimize the inconvenience to you.

If you would like to update your vehicle ownership or contact information, please go to www.toyota.com/ownersupdate. You will need your full 17-digit Vehicle Identification Number (VIN) to input the new information.

What if you have previously paid for repairs or replacement of your vehicle's Air Injection Pumps and/or Air Switching Valves?

If you have previously paid for the repair or replacement of the Air Injection Pumps and/or Air Switching Valves to address the condition described above, please mail a copy of your repair order, proof-of-payment, and proof-of-ownership to the following address for reimbursement consideration:

Toyota Motor Sales, U.S.A., Inc.
Toyota Customer Experience, WC 10
19001 South Western Avenue
Torrance, CA 90509

Include your name, address, and telephone number(s) in your request. Please allow 6 to 8 weeks to process your request.

We have sent this notice in the interest of your continued satisfaction with our products.

Sincerely, TOYOTA MOTOR SALES, U.S.A., INC.



Customer Support Program (CSP) - ZTQ
2007 to 2010 Model Year Tundra and
2008 to 2010 Model Year Sequoia Vehicles
Extension of Warranty Coverage for Air Injection Pumps and Air Switching Valves

BACKGROUND

In our continuing efforts to assure the best in customer satisfaction, Toyota is announcing a Customer Support Program (CSP) to extend the warranty coverage on the Air Injection Pumps and Air Switching Valves of 2007 to 2010 model year Tundra and 2008 to 2010 model year Seguoia vehicles.

Q1: What is the condition?

A1: Toyota has received reports of customer concerns regarding the illumination of the check engine light (Malfunction Indicator Light) due to moisture/water in the Air Injection Pumps and/or Air Switching Valves in the engines of a number of these vehicles. To assist dealers in the diagnosis and repair of these vehicles a TSB has been released.

Some of the vehicles covered by the TSB may be outside of the Toyota's New Vehicle Limited Powertrain Warranty due to age and/or mileage. To assure customers that we stand behind our product, we are offering a warranty extension on the Air Injection Pumps and Air Switching Valves on 2007 to 2010 Tundra and 2008 to 2010 Sequoia vehicles.

Q2: What is Toyota going to do?

A2: Toyota is offering a Warranty Coverage Extension (CSP) for the Air Injection Pumps and Air Switching Valves for the condition described above. This CSP is available for 10 years from the date of first use or 150,000 miles, whichever comes first. If the condition is verified, the dealer will replace the Air Injection Pumps and Air Switching Valves under the terms of this CSP.

Owners of 2007 to 2010 Model Year Tundra and 2008 to 2010 Model Year Sequoia vehicles covered by this CSP will receive an Owner Letter via first class mail starting in late October, 2011. Owners will be advised of the CSP coverage and in the event they encounter this condition within 10 years from the vehicles date of first use or before 150,000 miles, whichever comes first, to contact a Toyota dealership for diagnosis and repair. The repair will be conducted in accordance with the terms of the Warranty Extension (CSP).

Q3: What are the Air Injection Pumps and Air Switching Valves and what do they do?

A3: The Air Injection Pumps and Switching Valves are parts of the vehicle emissions system. The Air Injection system is designed to pump fresh air into the exhaust stream during a cold engine start; the fresh air helps speed the catalytic converter warm up time to reduce cold start emissions.

Q4: Which vehicles are covered by this CSP?

A4: There are approximately 477,000 Tundra (2007 to 2010 Model Year) and 57,000 Sequoia (2008 to 2010 Model Year) vehicles covered by this CSP.

MODEL	WMI	MY	VDS	UIO
			BT64A	182
			BY64A	6826
			BY67A	5604
SEQUOIA	5TD	2008	BY68A	10229
SEGUUIA	310	2000	ZT64A	100
			ZY64A	6126
			ZY67A	2213
			ZY68A	7010

MODEL	WMI	MY	VDS	UIO
			JV521	833
A			KT521	185
			KV521	724
TUNDRA	5TF	2008	LT521	150
TUNDRA	317	2000	LU521	937
			LV521	595
			MT521	124
				753

			DTCAA	004
			BT64A	891
			BW68A	1
			BY64A	4
		2009	BY67A	76
	•		BY68A	4
			ZT64A	515
			ZY64A	2
			ZY67A	1
			ZY68A	4
			BM5G1	150
			BW5G1	569
SEQUOIA	5TD			
0			BY5G1	1088
			DW5G1	3556
	1	2010	DY5G1	2283
			JW5G1	1687
			JY5G1	2145
			KM5G1	2
			KY5G1	1758
			YY5G1	2173
			ZM5G1	1224
	İ		ZY5G1	961
			ZY67A	2
			BT541	6655
			BT581	516
		[BV541	12412
			BV581	4186
			DT541	349
			DT581	54
			DV541	9642
		ļ	DV581	9539
		2007	ET541	1816
			ET581	198
		ļ	EV541	9769
		ŀ	EV581	5017
	1		RT541	5251
			RT581	401
			RU541	1750
TUNDRA	5TB		RV541	7135
TONDRA			RV581	1346
			BT541	6002
			BT581	3
			BV541	15886
			BV581	2953
			DT541	41
		2008	DT581	15
				4290
			DV541	·
			DV581	3523
			ET541	199
.:			ET581	2
			EV541	2783
			EV581	1060
			RT541	3764
			RT581	44
				5698
		1	RV541	nnua

RT541 RT581 RU541 2008 RV541 RV581 ST541 SV541 BV541 BV581 BV581 BW581 CT541 CV541 CV541 CW541 DV541 DV541 DV581	8140 42 9769 20125 1526 91 1465 802 2505 19 3164 137
2008 RU541 RV581 ST541 SV541 BT541 BV541 BV581 BV581 BW581 CT541 CV541 CV541 CW541 DV541 DV581	9769 20125 1526 91 1465 802 2505 19 3164
2008 RV541 RV581 ST541 SV541 BT541 BV541 BV581 BW581 CT541 CV541 CV541 CW541 DV541 DV581	20125 1526 91 1465 802 2505 19 3164
RV581 ST541 SV541 BT541 BV541 BV581 BW581 CT541 CV541 CV541 DV541 DV541	1526 91 1465 802 2505 19 3164
ST541 SV541 BT541 BV541 BV581 BW541 BW581 CT541 CV541 CV541 DV541 DV541	91 1465 802 2505 19 3164
SV541 BT541 BV541 BV581 BW541 BW581 CT541 CV541 CW541 DV541 DV541	1465 802 2505 19 3164
BT541 BV541 BV581 BW541 BW581 CT541 CV541 CW541 DT541 DV541	802 2505 19 3164
BV541 BV581 BW541 BW581 CT541 CV541 CW541 DT541 DV541	2505 19 3164
BV581 BW541 BW581 CT541 CV541 CW541 DT541 DV541	19 3164
BV581 BW541 BW581 CT541 CV541 CW541 DT541 DV541	19 3164
BW541 BW581 CT541 CV541 CW541 DT541 DV541 DV581	3164
BW581 CT541 CV541 CW541 DT541 DV541 DV581	
CT541 CV541 CW541 DT541 DV541 DV581	1 13/1
CV541 CW541 DT541 DV541 DV581	3
CW541 DT541 DV541 DV581	158
DT541 DV541 DV581	60
DV541 DV581	14
DV581	449
) <u> </u>	165
DW541	1353
DW581	523
ET541	32
EV541	1231
EV581	113
2009 JU521	78
JV521	23
}	6
KT521	70
TUNDRA 5TF KV521	11
KW521	
LT521	30
LU521	167
LV521	16
MT521	13
MV521	52
MW521	32
RT541	1492
RU541	2785
RV541	2420
RV581	41
ST541	9
SV541	70
BM5F1	18
BW5F1	1413
BY5F1	1620
CM5F1	315
CW5F1	658
CY5F1	903
2010 DM5F1	991
2010 DW5F1	7915
DY5F1	4871
EM5F1	3213
EY5F1	8997
EY5F1 FM5F1	
EY5F1 FM5F1 FY5F1	8997 12 2485

	5TB	2008	RV581	485
			BT541	5817
			BT581	719
			BV541	17921
			BV581	6479
			CT541	914
			CV541	3472
			DT541	5
			DT581	1
			DV541	1225
			DV581	1239
			ET541	9
			ET581	1
			EV541	2155
	5TF		EV581	875
			JT521	962
			JU521	2190
TUNDRA		2007 K K L L L M C	JV521	1264
			KT521	1122
			KV521	1319
			LT521	755
			LU521	2143
			LV521	889
			MT521	666
			CV541	3252
			DT541	139
			DT581	2
			DV541	11888
			DV581	8198
			ET541	1871
			ET581	6
			EV541	11105
			EV581	3365
			JT521	166
			JU521	780

			HW5F1	6235
1			HY5F1	3210
7			HY5F1 JM5F1 JU5F1 JY5F1 KM5F1 KW5F1 KY5F1 LW5F1 LU5F1 LY5F1 MM5F1 MW5F1 MY5F1 RW5F1 RW5F1 RW5F1 RY5F1 SY5F1 SY5F1 TM5F1	184
			JU5F1	344
			JY5F1	72
			KM5F1	225
	FUNDRA 5TF	2010	KW5F1	193
TUNDDA			KY5F1	304
			LM5F1	192
			LU5F1	859
			LY5F1	68
			MM5F1	272
TUNDRA			MW5F1	273
-			MY5F1	299
			RM5F1	15429
			RU5F1	2866
			RY5F1	11885
			SM5F1	19
			SY5F1	332
			TM5F1	237
			TY5F1	590
			UM5F1	11444
			UW5F1	15350
			UY5F1	13923

Q5: What is the production period of the vehicles covered by this CSP?

A5: The covered Toyota Tundra and Sequoia vehicles were produced from Early November 2006 through Mid-August, 2010.

Q6: Are there any other Toyota, Lexus or Scion vehicles covered by this CSP?

A6: No. This specific condition only affects 2007 to 2010 Model Year Tundra and 2008 to 2010 model year Sequoia vehicles.

Q7: What are the details of this coverage?

A7: This warranty extension is available for 10 years from the vehicles date of first use or 150,000 miles whichever comes first, for the condition described above related the Tundra/Sequoia's Air Injection Pumps and Air Switching Valves. The specific component(s) covered by this warranty extension are as follows:

- Air Injection Pump/s
- Air Switching Valves
- Air Pump Inlet/Cover
- Gaskets and Clamp

Please note that damage incurred from abuse, a crash, vandalism, or other similar events is not covered by the New Vehicle Limited Warranty or this Warranty Extension.

How long will the repair take?

The repair will take approximately 4 hours; however, depending upon the dealer's work schedule, it A8: may be necessary to make the vehicle available for a longer period of time.

What should an owner do if they experience a MIL "ON" condition? **Q9**:

Please have the customer contact their local Toyota dealer for appropriate diagnosis and repair. If the MIL "ON" condition is accordance with the terms of this CSP the repair will be performed at NO CHARGE.

Q10: Is there a problem with the Air Injection Pumps and Air Switching Valves in the covered Tundra and Sequoia vehicles.

All vehicles comply with Toyota's rigorous durability and quality standards. The condition impacts only A10: a small number of Air Injection Pumps and Air Switching Valves. The warranty extension reflects Toyota's desire to assure our customers that Toyota stands behind its products.

What was changed to prevent this condition from re-occuring?

The air inlets for the Air Injection Pumps now contain a newly designed cover (shield) to prevent water/moisture from entering the Air Injection Pumps and Switching Valves.

What if a customer has previously paid for repairs on their vehicle?

Owners that have previously paid for repairs for this specific condition should refer to the owner letter A12: for reimbursement consideration instructions.

What if an owner has additional questions or concerns?

Owners with questions or concerns are asked to please contact the Toyota Customer Experience A13: Center at 1-888-270-9371 Monday through Friday, 5:00 am to 6:00 pm, or Saturday 7:00 am through 4:00 pm Pacific Time



Toyota Motor Sales, U.S.A., Inc. 19001 South Western Avenue P.O. Box 2991 Torrance, CA 90509-2991

2007 to 2010 Model Year Tundra and 2008 to 2010 Model Year Sequoia Vehicles Air Injection Pumps and Air Switching Valves WARRANTY ENHANCEMENT NOTICE

Dear Sequoia Owner:

At Toyota, we are dedicated to providing vehicles of outstanding quality and value. As part of our continual efforts to meet your product expectations, Toyota would like to advise you of an extension to portions of your Sequoia's vehicle warranty.

Toyota cares about our customers

Toyota has received reports of customer concerns regarding the illumination of the check engine light (Malfunction Indicator Light) due to moisture/water in the Air Injection Pumps and/or Air Switching Valves in the engines of a number of these vehicles. To assist dealers in the diagnosis and repair of these vehicles a Technical Service Bulletin (TSB) has been released.

Some of the vehicles covered by the TSB may be outside of the Toyota's New Vehicle Limited Powertrain Warranty due to age and/or mileage. To assure customers that we stand behind our product, we are offering a warranty extension on the Air Injection Pumps and Air Switching Valves on 2007 to 2010 Tundra and 2008 to 2010 Seguoia vehicles.

Warranty Enhancement

The Air Injection Pumps and Air Switching Valves are covered by Toyota's New Vehicle Limited Powertrain Warranty for 5 years or 60,000 miles from the date of first use (whichever comes first) and by the California Emission Warranty* for 7 years or 70,000 miles from the date of first use (whichever comes first).

The Warranty Coverage Extension for the Air Injection Pumps and Air Switching Valves for the condition described above will extend the warranty coverage to 10 years from the date of first use or 150,000 miles, whichever comes first. If the condition is verified, the dealer will replace the Air Injection Pumps and Air Switching Valves under the terms of this Warranty Coverage Extension.

Please note that damage incurred from abuse, a crash, vandalism or other similar events is not covered by the New Vehicle Limited Warranty or this Warranty Extension.

*The California Emission Warranty coverage only applies to certain states and certain model year/engine type Tundra and Sequoia vehicles. Please refer to your vehicle's Toyota Owner's Warranty Information Booklet for details and applicability.