

1	Sudden Acceleration and Engine Surging	Self-actuation	1985	DP85-031	PE85-065	n/a	n/a	Ford	1984 - 1984 Full and Midsize Ford	??
2	Sudden Acceleration	Vehicle features related to PM	1985	PE85-008	EA85-029	n/a	n/a	Nissan	1979 - 1987 280 and 300Z	184,000
3	Engine Surge	Self-actuation	1985	PE85-030	n/a	n/a	n/a	GM	1982 - 1985 J cars	Unk
4	Unwanted Vehicle Acceleration	Vehicle features related to PM	1985	PE85-042	EA85-043	n/a	n/a	AMC	1983 - 1984 Alliance and Encore	310,000
5	Throttle Sticking	Stuck throttle	1985	PE85-051	n/a	n/a	n/a	GM	1979 - 1982 Chevette	Unk
6	Throttle Sticks	Stuck throttle	1985	PE85-056	n/a	n/a	n/a	Mazda	1981 - 1982 GLC	Unk
7	Uncontrollable Acceleration	Self-actuation	1986	DP86-005	n/a	n/a	n/a	GM	1979 Pontiac Bonneville	??
8	Sudden Acceleration	Vehicle features related to PM	1986	DP86-006	PE86-010	EA86-016	C86-001	VW/Audi	1978 - 1986 Audi 5000	254,000
9	Sudden Acceleration	Self-actuation	1986	DP86-007	EA85-045	n/a	n/a	Toyota	1981 - 1986 Cressida	135,000
10	Sudden Acceleration	Vehicle features related to PM	1986	DP86-008	n/a	n/a	n/a	Toyota	1983 - 1984 Camry	??
11	Uncontrolled Acceleration	Vehicle features related to PM	1986	DP86-009	n/a	n/a	n/a	VW/Audi	1980 Rabbit Diesel	??
12	Sudden Acceleration	Vehicle features related to PM	1986	DP86-014	n/a	n/a	n/a	Ford	1981 Taurus	??
13	Sudden Acceleration	Vehicle features related to PM	1986	DP86-019	EA87-007	n/a	n/a	GM	1982 - 1985 J cars	2,174,000
14	Throttle Non-return	Stuck throttle	1986	PE86-012	EA86-013	EA88-023	C89-001	GM	1984 - 1988 GM B,C,D,E,G,H,K & W BODY	2,600,000
15	Sudden Acceleration	Vehicle features related to PM	1986	PE86-050	n/a	n/a	n/a	Volvo	1980 - 1986 All Models	Unk
16	Sudden Acceleration	Vehicle features related to PM	1986	PE86-066	n/a	n/a	n/a	Honda	1984 - 1986 Accord	746,000
17	Sudden Acceleration	Vehicle features related to PM	1986	PE87-001	n/a	n/a	n/a	Daimler/MB	1986 300E	22,000
18	Sudden Acceleration	Vehicle features related to PM	1987	DP87-002	n/a	n/a	n/a	VW/Audi	1979 - 1986 Audi 4000	??
19	Sudden Acceleration	Vehicle features related to PM	1987	DP87-003	EA87-021	n/a	n/a	Ford	1983 - 1986 3.8 and 5.0 l Ford engines	3,134,000
20	Sudden Acceleration	Vehicle features related to PM	1987	DP87-006	EA87-012	n/a	n/a	Honda	1986 - 1987 Accord	91,000
21	Sudden Acceleration	Vehicle features related to PM	1987	DP87-019	EA88-003	n/a	n/a	Daimler/MB	1986 - 1988 300E	54,000
22	Sudden Acceleration	Vehicle features related to PM	1987	DP87-026	n/a	n/a	n/a	Honda	1984 Honda Accord	??
23	Sudden Acceleration	Vehicle features related to PM	1987	DP87-026	PE87-041	EA88-010	n/a	GM	1986 - 1987 GM H cars (LeSabre, Bonneville, Delta)	1,081,000
24	Sudden Acceleration	Vehicle features related to PM	1987	PE87-018	n/a	n/a	n/a	Chrysler	1985 - 1986 Dodge Colt	172,000
25	Throttle Sticking	Stuck throttle	1987	PE87-061	n/a	n/a	n/a	Alpha Romeo	1985 Spyder	4,000
26	Sudden Acceleration	Vehicle features related to PM	1988	DP88-005	EA88-026	n/a	n/a	Honda	1986 - 1988 Acura Legend	118,000
27	Sudden Acceleration	Vehicle features related to PM	1988	DP88-008	n/a	n/a	n/a	Honda	1986 Accord	??
28	Sudden Acceleration	Vehicle features related to PM	1988	DP88-009	EA88-031	n/a	n/a	GM	1985 - 1988 C cars	1,300,000
29	Sudden Acceleration	Vehicle features related to PM	1988	DP88-013	EA88-034	n/a	n/a	Daimler/MB	1984 - 1988 models with gas engines	255,000
30	Throttle Sticking/Logic Module	Stuck throttle	1988	DP88-017	EA89-001	n/a	n/a	Chrysler	1997 Plymouth Sundance	346,000
31	Throttle Control	Vehicle features related to PM	1988	PE88-029	n/a	n/a	n/a	Chrysler	1987 - 1988 Jeep	123,000
32	Throttle Cable Binding	Stuck throttle	1988	PE88-033	n/a	n/a	n/a	GM	1984 Pontiac Fiero	126,000
33	Sudden Acceleration	Vehicle features related to PM	1988	PE88-082	n/a	n/a	n/a	International	1985 - 1988 School Bus	Unk
34	Cruise Control Response	Self-actuation	1988	PE88-090	n/a	n/a	n/a	GM	1988 G vans w/6.2l diesel	500
35	Floor mat/Accel Pedal Infrf	Stuck throttle	1988	PE88-097	n/a	n/a	n/a	Ford	1987 - 1988 Thunderbird	592,000
36	Sudden Acceleration	Vehicle features related to PM	1989	DP89-004	n/a	n/a	n/a	GM	1982 - 1988 Cadillac w/4.1l engine	??
37	Throttle Plate Jams Open	Stuck throttle	1989	PE89-019	n/a	n/a	n/a	Ford	1981 - 1988 Truck and School Bus w/370 engine	128,000
38	Electronic Accel	Stuck throttle	1989	PE89-028	n/a	n/a	n/a	Dana Corp	Pedal Assembly Electric/Electronic	3,400
39	Cruise Control Erratic	Self-actuation	1989	PE89-095	n/a	n/a	n/a	Chrysler	1987 Jeep	148,000
40	Cruise Control	Self-actuation	1989	PE89-097	n/a	n/a	n/a	GM	1988 Chevy Suburban and GMC Jimmy	102,000
41	Throttle Grip Sticks	Stuck throttle	1989	PE89-149	n/a	n/a	n/a	Yamaha	1989 FZR	10,000
42	Throttle Cable Sticks	Stuck throttle	1989	PE89-163	n/a	n/a	n/a	Lag	1987 - 1988 Motor coach	100
43	Throttle Sticking	Vehicle features related to PM	1990	PE90-001	EA90-009	n/a	n/a	Ford	1988 - 1989 Thunderbird	454,000
44	Cruise Control Failure	Stuck throttle	1990	PE90-014	n/a	n/a	n/a	GM	1984 - 1987 Regal and Cutlass Supreme	743,000
45	Throttle Sticking	Stuck throttle	1990	PE90-066	EA90-042	n/a	n/a	Ford	1986 - 1989 Ford products with 2.3, 2.9 & 3.0l engines	2,649,000
46	Throttle Linkage Fails	Stuck throttle	1990	PE90-081	n/a	n/a	n/a	Renault	1988 - 1989 Medallion	30,000
47	Diesel Engine Surge	Stuck throttle	1990	PE90-087	n/a	n/a	n/a	Isuzu	1986 - 1990 Trooper w/Turbo	3,000
48	Throttle Return Spring (not in Artemis)	Stuck throttle	1990	SO90-013	n/a	n/a	n/a	Chance Coach	1987 - 1990 Sunliner	Unk
49	Throttle Linkage Interference	Vehicle features related to PM	1991	PE91-029	n/a	n/a	n/a	GM	1991 Cadillac Deville and Fleetwood w/4.5l	225,000
50	Throttle Release Failure	Stuck throttle	1991	PE91-058	EA91-034	n/a	n/a	Ford	1991 Explorer	344,000
51	Throttle Sticking	Self-actuation	1991	PE91-088	n/a	n/a	n/a	Mazda	1986 - 1991 MPV, MX6, 626 & 929	640,000
52	Throttle Sticks, High Idle	Self-actuation	1991	PE91-089	n/a	n/a	n/a	Ford	1990 Mustang w/5.0l	42,000
53	Governor Pin/Eng Throttle	Stuck throttle	1991	PE91-103	EA91-050	n/a	n/a	Caterpillar	1988 Trucks with 3406B & 3306B engines	113,000
54	Throttle Sticking	Stuck throttle	1991	PE91-131	EA92-005	n/a	n/a	GM	1985 - 1988 Firebird, Camaro & Corvette with 5.0 & 5.7 l engines	338,000
55	Sudden Acceleration	Vehicle features related to PM	1992	DP92-009	n/a	n/a	n/a	Nissan	1987 Maxima	184,000
56	Throttle Sticking	Stuck throttle	1992	PE92-021	EA92-024	n/a	n/a	GM	1987 - 1991 A, J, L & W w/2.8l engine	1,400,000
57	Throttle Sticking	Stuck throttle	1992	PE92-065	EA92-044	n/a	n/a	Toyota	1987 - 1989 Camry and Celica w/2.0l engine	892,000
58	Throttle Sticking/Binding	Stuck throttle	1992	PE92-090	EA93-012	n/a	n/a	GM	1989 - 1990 Caprice Checker Cab	9,000
59	Throttle Return Spring (not in Artemis)	Stuck throttle	1992	SO92-008	n/a	n/a	n/a	Chance Coach	1987 - 1991 Sunliner	Unk
60	Throttle Sticking	Stuck throttle	1993	EA91-034	EA93-003	n/a	n/a	Ford	1991 Explorer Eddie Bauer Edition	93,000
61	Cruise Control Malfunction	Stuck throttle	1993	PE93-011	n/a	n/a	n/a	Ford	1986 - 1988 Mustangs	167,000
62	Throttle Linkage Interference	Stuck throttle	1993	PE93-014	n/a	n/a	n/a	Damon Motor C	1992 Challenger w/Cummins engines	30
63	Melted Throttle Cable	Stuck throttle	1993	PE93-056	n/a	n/a	n/a	Chrysler	1989 - 1993 Caravan, Voyager & Town and Country	885,000
64	Throttle Not Returning	Stuck throttle	1993	PE93-069	n/a	n/a	n/a	Ford	1993 L Series Trucks	20,000

65	Accelerator and Brake Pedal Placement	Vehicle features related to PM	1994	PE94-014	EA94-021	n/a	n/a	International	1990 - 1992 Navistar 3800 School Bus	23,000
66	Cruise Control Malfunction	Stuck throttle	1994	PE94-029	n/a	n/a	n/a	Mazda	1993 Protégé	77,000
67	Cruise Control Failures	Stuck throttle	1994	PE94-079	EA95-003	n/a	n/a	GM	1993 - 1995 Saturn models with CC	401,000
68	Sudden Acceleration	Vehicle features related to PM	1995	DP95-007	n/a	n/a	n/a	Chrysler	1991 - 1995 Jeep Cherokee	??
69	<i>Stuck Engine Throttle (not in Artemis)</i>	Stuck throttle	1995	RQ95-010	n/a	n/a	n/a	International	1989 - 1991 3700/3800 School Bus	Unk
70	Binding Throttle Hand Controls	Stuck throttle	1996	PE96-023	n/a	n/a	n/a	Drive-Master	1994 - 1996 Ultralite XL	2,600
71	Throttle Will Not return to the Closed Position	Stuck throttle	1996	PE96-036	n/a	n/a	n/a	Chrysler	1991 - 1992 Chrysler Models	638,000
72	Throttle Sticking	Stuck throttle	1998	DP98-016	PE98-016	EA98-022	n/a	Jaguar/Tata	1994 XJ12	1,500
73	Accelerator Return Springs	Stuck throttle	1998	EQ98-004	n/a	n/a	n/a	Cummins	1992 - 1995 Engines	Unk
74	Loss of Throttle Control	Stuck throttle	1998	PE98-021	EA98-018	n/a	n/a	Ford	1997 - 1998 F150	1,000,000
75	Ice Formation in the Throttle Body	Stuck throttle	1998	RQ98-003	n/a	n/a	n/a	Ford	1997 F-150 w/4.6, 5.4 & 6.8l engines	1,418,000
76	Throttle Sticking	Stuck throttle	1998	SQ98-014	EA99-001	n/a	n/a	Ford	1997 - 1998 Explorer w/4.0l SOHC	447,000
77	Throttle Cable Sticking	Stuck throttle	1998	SQ98-017	n/a	n/a	n/a	Honda	1996 - 1998 Honda Civic	936,000
78	Throttle Return Spring	Stuck throttle	1998	SQ98-025	n/a	n/a	n/a	Freightliner	1997 - 1998 MT10, MT12, MT13 & MT35 trucks	1,800
79	Sudden Acceleration	Vehicle features related to PM	1999	DP99-004	n/a	n/a	n/a	Ford	1998 Town Car and other models w/CC	6,061,000
80	Shift-Lock	Vehicle features related to PM	1999	PE99-022	n/a	n/a	n/a	Ford	1991 - 1999 Various Models	11,289,000
81	Loss of Throttle Control	Stuck throttle	2000	PE00-048	n/a	n/a	n/a	Chrysler	1994 - 1996 Dodge Ram 2500/3500	157,000
82	Throttle Pedal Fails to Return	Stuck throttle	2001	PE01-030	n/a	n/a	n/a	Amtran	1997 - 2000 3800 Bus	1,400
83	Sudden Acceleration	Self-actuation	2002	DP02-005	n/a	n/a	n/a	Chrysler	19991 - 1995 Jeep Cherokee and Grand Cherokee	1,302,000
84	Throttle Sticking	Stuck throttle	2002	PE02-021	EA02-015	n/a	n/a	GM	1999 - 2002 Silverado, Sierra, Tahoe, Suburban, Avalanche, Yukon	3,401,000
85	Brake/Accel Pedal Separation	Vehicle features related to PM	2002	PE02-035	n/a	n/a	n/a	Ford	2000 - 2001 Taurus & Sable	370,000
86	Unintended Engine Speed Increase/SA	Vehicle features related to PM	2003	DP03-003	n/a	n/a	n/a	Toyota	1997 - 2000 Lexus LS and GS	600,000
87	Unintended Vehicle Acceleration	Vehicle features related to PM	2003	DP03-007	n/a	n/a	n/a	GM	1996 - 1997 Chevy Cavalier and Pontiac Sunbird	761,000
88	Throttle Control Failure	Vehicle features related to PM	2003	PE03-010	n/a	n/a	n/a	Chrysler	1998 - 2003 LHS, Concorde, Intrepid, & 300M	1,140,000
89	Throttle Fails to Return to Idle	Stuck throttle	2003	PE03-043	n/a	n/a	n/a	Buell/HD	1995 - 2001 S1, S1T, S2, S2T, S3, S3T, M2 & X1	2,800
90	Throttle Control System	Vehicle features related to PM	2004	DP04-003	PE04-021	n/a	n/a	Toyota	2002 - 2003 Camry & ES	982,000
91	Loss of Throttle Control	Stuck throttle	2004	PE04-006	n/a	n/a	n/a	EMC	Aevis DL-001	600
92	Stuck-open Throttle	Stuck throttle	2004	PE04-023	EA04-017	n/a	n/a	VW/Audi	1998 - 1999 Audi A4/A6 and VW Passat	106,000
93	Throttle Cable Binding	Stuck throttle	2004	PE04-067	n/a	n/a	n/a	Kia	2002 - 2004 Sedona	89,000
94	Vehicle Speed Control	Vehicle features related to PM	2005	DP05-002	n/a	n/a	n/a	Toyota	2002 - 2005 Camry, Solara & ES	1,950,000
95	Accelerator Pedal Interference	Stuck throttle	2005	PE05-038	EA05-014	n/a	n/a	Ford	2003 - 2004 Mustang Cobra	19,000
96	Stuck Engine Throttle	Stuck throttle	2005	PE05-092	n/a	n/a	n/a	Ford	2002 Explorer and Mountaineer w/4.0l SOHC	234,000
97	Unintended Acceleration	Vehicle features related to PM	2006	DP06-002	n/a	n/a	n/a	Chrysler	2006 Jeep Commander	263,000
98	Engine Surging	Vehicle features related to PM	2006	DP06-003	n/a	n/a	n/a	Toyota	2002 - 2006 Camry & Solara	1,861,000
99	Unwanted Acceleration, Floor Mat	Stuck throttle	2007	PE07-016	EA07-010	n/a	n/a	Toyota	2007 - 2008 Camry and ES	55,000
100	Stuck Throttle Valve	Stuck throttle	2007	PE07-051	EA08-005	n/a	n/a	GM	2004 - 2005 Aveo	119,000
101	Sudden and Uncontrolled Acceleration	Vehicle features related to PM	2008	DP08-001	n/a	n/a	n/a	Toyota	2006 - 2007 Tacoma	360,000
102	Accelerator Pedal Interference	Stuck throttle	2008	PE08-025	EA08-014	n/a	n/a	Toyota	2004 Sienna	27,000
103	Accelerator Pedal -Floor Mat Interference	Stuck throttle	2008	PE08-039	n/a	n/a	n/a	Weathertech	Accessory Floor mats	119,000
104	Unwanted and Unintended Acceleration	Stuck throttle	2009	DP09-001	n/a	n/a	n/a	Toyota	2002 - 2003, & 2007 ES	231,000
105	Throttle Sticks On Floor Plate	Stuck throttle	2009	PE09-047	n/a	n/a	n/a	Thomas Bus	2006 - 2010 EF Bus	5,100
106	CTS Accelerator Pedal Assemblies	Stuck throttle	2010	EQ10-002	n/a	n/a	n/a	CTS	Pedals with certain plastic materials	Unk
107	Sticking Accelerator Pedal	Stuck throttle	2010	PE10-012	n/a	n/a	n/a	Chrysler	2007 Caliber	161,000
108	Accelerator Pedal Entrapment	Stuck throttle	2010	PE10-019	tbd	tbd	tbd	Ford	2010 Fusion w/accessory mat	249,000
109	Unintended Acceleration	Vehicle features related to PM	2010	RQ10-003	tbd	tbd	tbd	Toyota	All models with ETC	7,709,000