



**NUMBER:** 05-003-11

**GROUP:** Brakes

**DATE:** February 18, 2011

**SUBJECT:**

Brake Front Pad Lining Life

**OVERVIEW:**

This bulletin involves installing new brake linings and replacing both brake rotors as required.

**MODELS:**

2009 (JC) Journey

**NOTE:** This Bulletin applies to vehicles built for the 2009 model year sold in U.S. and Canada (sales code YAA and YAC) markets only.

**SYMPTOM/CONDITION:**

Front brake pads may exhibit lining life complaints.

**POLICY:**

Reimbursable within the provisions of the warranty.

Vehicles included in this Service Bulletin have a Warranty Extension for this repair. See Warranty Bulletins; U.S. D-11-07, Canada CA-2011-05 for details associated with the extended warranty.

**TIME ALLOWANCE:**

Labor Operation No:	Description	Amount
05-21-10-9A	Inspect Front Brake Pads And Rotors Both Sides (C)	0.3 Hrs.
05-21-10-9B	Replace Front Brake Pads And Front Brake Rotors Both Sides (C)	0.7 Hrs.